



**Republic of Iraq**

**Ministry of Culture, Tourism and Antiquities**

**State Board of Antiquities & Heritage**

**World Heritage Department**

**State of Conservation Report**

**Hatra**

**In response to the extended 46<sup>th</sup> session of the World**

**Heritage Committee, New Delhi, India 2024**

**Decision: 46 COM 7A.15**

**By**

**Zuhoor Abbas Lafta**

**Mahmoud Abdullah Wardi**

**(Head of translation division)**

**(Hatra Site Manager)**

**Muthanna Abid Dawood**

**(World Heritage Department Director)**

**Baghdad**

**November.2024**

**Name of the / property** Hatra

**State party / Iraq**

**ID / c277rev**

**Criteria: (ii)(iii)(iv)(vi)**

**Date of Inscription: 1985**

***The World Heritage Committee,***

- 1. Having examined Document WHC/24/46.COM/7A,*
- 2. Recalling Decisions **45 COM 7A.28** and **45 COM 7A.30** adopted at its extended 45th session (Riyadh, 2023),*
- 3. Commends the efforts undertaken in the implementation of previous Committee Decisions and corrective measures for the achievement of the Desired state of conservation for the removal of the property from the List of World Heritage in Danger (DSOCR), as adopted by the Committee in Decision **45 COM 7A.28**;*
- 4. Encourages the State Party to pursue the implementation and completion of other corrective measures as a priority, and to seek any necessary further support, in particular for:*
  - a) Reinforcing site security (installation of surveillance cameras), State of conservation of the properties WHC/24/46.COM/7A, p. 35 inscribed on the List of World Heritage in Danger*
  - b) Repairing damage resulting from conflict (completing the temporary transport of archaeological finds to be photographed and catalogued, as well as ensuring their adequate storage and protection),*
  - c) Assessing risks at monuments indirectly impacted by the conflict and addressing vulnerabilities, including through assessment, studies and urgent stabilization (diagnostic studies and planning for restoration*

*works at the Temples of Samya, the Triad, and Allat; priority interventions at the Temples of Shahiru and Allat; preparation of a Conservation Plan for the central Temenos area);*

*5. Acknowledges with appreciation the efforts undertaken in addressing the recommendations of the 2023 joint World Heritage Centre/ICOMOS Reactive Monitoring mission, and reiterates its request to further implement the mission's recommendations, in particular addressing the following:*

*a) Elaboration of a monitoring programme, coupled with a capacity building programme to implement it,*

*b) Preparation of the Conservation Plan for the central Temenos area, and*

*subsequent selection of pilot interventions and monitoring them over time to assess their efficacy;*

*c) Further assessment of potential threats, such as those that may be related to archaeological remains, in the area between the inner and outer city walls as necessary, and accordingly elaboration of additional possible protection measures,*

*d) Initiating the preparation of a site Management Plan that includes consideration requirements related to management and conservation, and a Visitor Management Plan,*

*e) Preparation of a strategy and allocation of resources for documentation management;*

*6. Taking note of the State Party's intention to submit a boundary clarification for the property, also encourages the State Party to consider the elaboration of a Minor Boundary Modification proposal for the designation of a buffer zone, for added protection of the property, in conformity with paragraphs 163-164 of the Operational Guidelines;*

7. *Recalls the need for the State Party to submit to the World Heritage Centre, for review by the Advisory Bodies, detailed information on all planned and ongoing works that may have an impact on the Outstanding Universal Value of the property, including Heritage Impact Assessments prepared in accordance with the Guidance and Toolkit for Impact Assessments in a World Heritage Context for any major projects, and to do so before making any decisions that will be difficult to reverse, in conformity with Paragraph 172 of the Operational Guidelines;*
8. *Calls again on all States Parties to support emergency safeguarding measures, including through the UNESCO Heritage Emergency Fund;*
9. *Also requests the State Party to submit to the World Heritage Centre, by **1 February 2025**, an updated report on the state of conservation of the property and the implementation of the above, for examination by the World Heritage Committee at its 47th session;*
10. ***Decides to retain Hatra (Iraq) on the List of World Heritage in Danger.***

**:Executive summary**

**First: Corrective measures in theTemenosarea (2024).**

**Second: Temporary transfer of artifacts to photograph and index them and ensure their storage and protection.**

**Third: Maintenance of theTemenosarea .**

**Fourth: Preparation of a monitoring program.**

**Fifth: Potential threats to archaeological remains located between the inner and outer city walls.**

**Sixth: Preparation of a site management and visitor management plan.**

### **First: Corrective measures in the Temenos area (2024)**

Among the corrective measures that were carried out in the main **Temenos** area in cooperation with the ASMEO team, one of the columns of the portico opposite the great temple (the Temple of the Sun) was rebuilt near the western side of the Temple of Shehero (see pictures 1 and 2) which was destroyed by ISIS terrorist gangs when they occupied the archaeological site by using the columns as targets to train their members to shoot. They are rebuilt using old stones and returned to their natural state, as well as rebuilding the upper space above the column that connects it to the columns at a distance of 4 meters, using the same original material that connects the column pieces.



**Image No. 1**



**Image No. 2**

**Second: Temporary transfer of artifacts to photograph and index them and ensure their storage and protection**

After liberating the archaeological site from the terrorist ISIS gangs and returning the control of the State Board of Antiquities and Heritage / Nineveh Antiquities and Heritage Inspectorate, on the archaeological site, we participated with the ASMEO mission team to collect all the artifacts that were found scattered in different parts of the archaeological site during the ISIS occupation period. They were transferred and placed in a safe place. Warehouses were prepared to preserve the artifacts and iron

benches were made in the form of shelves to place the artifacts on (see Image No. 3). During 2024, a large number of these artifacts were documented and numbered and placed in these warehouses. In addition, other warehouses were cleaned and prepared to make them ready to put the remaining artifacts that had not been documented and numbered yet, awaiting the return of the aforementioned mission to complete the remaining work of the mission. In addition, there are two important large archaeological artifacts near the antiquities storage warehouse, and they cannot be brought into the warehouse due to their large size and the cracks in them, so iron canopies were made for them to protect them from weather and climate conditions.



**Image No.3**

### **Third: Maintenance of the Temenos Area**

Based on the directives of the head of the State Board of Antiquities and Heritage, a joint committee was formed from the State Board of Antiquities and Heritage and the Nineveh Antiquities and Heritage Inspectorate on 2/11/2024. This committee conducted a field visit to



Hatra archaeological site in order to prepare the necessary lists for the maintenance and restoration of the archaeological buildings in the Temenos area that needs urgent maintenance work after the Iraqi government allocated funds for this purpose. The list included the following buildings

- 1- Treating the bulges in the walls of the Great Temple (the southern side of the northern Iwan) and (the southern side of the southern Iwan).
- 2- Maintenance of the Temple of Alat.
- 3- Maintenance of the Temple of Trinity to preserve the upper part of the temple.
- 4- Maintenance and treatment of the trouble in the arch of the middle Iwan of the Temple of Sumayyah.
- 5- Maintenance of part of the southern side of the temples wall.
- 6- Treating cracks in the roofs of the archaeological buildings.
- 7- Removal and lifting of rubble near the eastern side of the Temenos area.
- 8- Removing the base of the tower crane. After the tower crane that was erected near the Temple of Al-Lat was dismantled and moved outside the Temenos area, its base remained made of reinforced concrete, so it had to be removed from the Temenos area.
- 9- Restoration of Sanitary facilities due to the site's urgent need for them, especially after the recent activity of tourism.

#### **Fourth: Preparing a monitoring program**

Among the things that have a direct impact on the archaeological site are the weather and climate conditions, as well as the growth of natural plants on the uncovered floors of the temples, which require continuous treatment and removal, in addition to the problem of moisture coming down from the roofs of buildings due to the presence of cracks in the

roofs of the archaeological buildings that allow rainwater to seep into the walls, as well as the problem of moisture coming up from the floors of the Temenos. As for human activities, they are hardly mentioned because the boundaries of the archaeological site are known to all residents of the area, and there are no projects that have a direct impact on the archaeological site, such as factories and other activities.

#### **Fifth: Potential threats to the archaeological remains located between the inner and outer city walls**

With regard to the threats to the archaeological remains between the city walls, after fencing the site with a (P.R.C) fence, the archaeological city became protected from all sides and entry to the site is through one gate on the eastern side under the protection of the security forces in addition to the presence of the Antiquities Protection Police Center where the center's members conduct field tours along the fence path around the archaeological city to protect it from any violations that may occur.

#### **Sixth: Preparing a site management and visitor management plan**

With regard to site management, it was supposed to prepare a plan to manage the site in cooperation with the (ASMEO) mission working at the archaeological site, but due to the delay in the return of the aforementioned mission due to the lack of funding, a plan has not been prepared yet.

As for visitor management, it is necessary to have a center to receive visitors and determine their paths and provide audio or visual aids with a cadre of tourist guides to accompany tourist delegations, especially after the recent activity of the tourist movement.

Among the things that can be added to this report regarding the activities inside the archaeological site during the year 2024, on 29/2/2024, the

Hatra Spirit Revival Festival was held sponsored by the Ministry of Tourism, Culture and Antiquities and under the direct supervision of the State Board of Antiquities and Heritage and the Nineveh Antiquities and

Heritage Inspectorate. The festival was attended by important figures from the Iraqi government, represented by the President of the Republic, the Minister of Culture, Tourism and Antiquities, the Chairman of the State Board of Antiquities and Heritage, the Governor of Nineveh, the Chairman of the Council and members of the Nineveh Provincial Council, foreign figures, tribal sheikhs, civil society activists and a large crowd from all Iraqi governorates (see photo No. 4).



Image No. 4

Ali Obaid Shalgham  
State Board of Antiquities and Heritage/ Head  
11/2024

Muthanna Abid Dawood  
World Heritage Department/Director  
27/ 11/2024

اسم الممتلك / الحضر

الدولة الطرف / العراق

رقم التعريف / c277rev

المعايير / (ii)(iii)(iv)(vi)

الملخص التنفيذي:

اولاً: التدابير التصحيحية في منطقة المعابد (٢٠٢٤)

ثانياً: النقل المؤقت للقطع الاثرية لتصويرها وفهرستها وضمان تخزينها وحمايتها

ثالثاً: صيانة منطقة المعابد

رابعاً: اعداد برنامج للمراقبة

خامساً: التهديدات المحتملة على البقايا الاثرية الواقعة بين اسوار المدينة الداخلية والخارجية

سادساً: اعداد خطة ادارة الموقع وادارة الزوار

## اولاً: التدابير التصحيحية في منطقة المعابد (٢٠٢٤)

من التدابير التصحيحية التي تم اجراءها في منطقة المعابد الرئيسية بالتعاون مع فريق منظمة (ASMEO) حيث تم اعادة بناء احد اعمدة الرواق المقابل للمعبد الكبير (معبد الشمس) بالقرب من الضلع الغربي لمعبد شحيرو (انظر صورة رقم ١ و ٢) والذي دمرته عصابات داعش الارهابية عند احتلالها الموقع الاثري من خلال اتخاذ من الاعمدة كأهداف لتدريب عناصرهم على اطلاق النار، وقد تم اعادة بنائه باستخدام الحجارة القديمة وارجاعه الى وضعه الطبيعي وكذلك اعادة بناء الفضاء العلوي فوق العمود الذي يربط بينه وبين الاعمدة بمسافة ٤ متر مع استخدام المادة الرابطة بين قطع العمود وبنفس المادة الاصلية.



(صورة رقم ٢)



(صورة رقم ١)

## ثانياً: النقل المؤقت للقطع الاثرية لتصويرها وفهرستها وضمان تخزينها وحمايتها

بعد تحرير الموقع الاثري من عصابات داعش الارهابية واستلام الموقع الاثري من قبل الهيئة العامة للآثار والتراث / مفتشية اثار وتراث نينوى قمنا بالاشتراك مع فريق بعثة منظمة (ASMEO) بجمع كل القطع الاثرية التي وجدت مبعثرة في اجزاء مختلفة من الموقع الاثري خلال فترة احتلال داعش وتم نقلها ووضعها في مكان امن وتم تهيئة مخازن لحفظ الاثار وعمل مساطب حديدية لى شكل رفوف لوضع القطع

الاثريّة عليها (انظر صورة رقم ٣) وخلال عام ٢٠٢٤ تم توثيق وترقيم عدد كبير من هذه القطع ووضعها في هذه المخازن ، يضاف الى ذلك تنه ايضا تم تنظيف مخازن اخرى وتهيتها لاستيعاب ما تبقى من القطع الاثريّة والتي لم يتم توثيقها وترقيمها بعد بانتظار عودة البعثة المذكورة اعلاه لإكمال ما تبقى من اعمال البعثة.

اضافه الى ذلك يوجد قطعتين اثريّة مهمّة ذات حجم كبير قرب مخزن حفظ الاثار ولا يمكن ادخالها الى المخزن لكبر حجمها ووجود تشققات فيها لذلك تم عمل سقائف حديدية لها حمايتها من الظروف الجوية والمناخية.



( صورة رقم ٣ )

### ثالثاً: صيانة منطقة المعابد

بناءً على توجيهات السيد رئيس الهيئة العامة للآثار والتراث تم تشكيل لجنة مشتركة من الهيئة العامة للآثار والتراث ومفتشية اثار وتراث نينوى بتاريخ ٢٠٢٤/١١/٢ قامت هذه اللجنة بزيارة ميدانية الى موقع اثار الحضر من اجل اعداد كشوفات لازمة لصيانة وترميم المباني الاثريّة في منطقة المعابد والتي تحتاج الى اعمال صيانه عاجلة بعد ان تم تخصيص مبالغ من الحكومة العراقية لهذا القرض وقد شمل الكشف المباني التالية

- ١- معالجة الانتفاخات الحاصلة في جدران المعبد الكبير (الضلع الجنوبي من الايوان الشمالي) و (الضلع الجنوبي من الايوان الجنوبي).
- ٢- صيانة معبد الات
- ٣- صيانة معبد التثليث للحفاظ على الجزء العلوي من المعبد.
- ٤- صيانة ومعالجة الخلل الموجود في قوس الايوان الوسطي لمعبد سمية.
- ٥- صيانة جزء من الضلع الجنوبي لسور المعابد.
- ٦- معالجة التشققات في سطوح المباني الاثرية.
- ٧- ازالة ورفع الانقاض بالقرب من الضلع الشرقي لمنطقة المعابد
- ٨- ازالة قاعدة تور كرين فبعد ان تم تفكيك تور كرين الذي كان منصوب قرب معبد اللات ونقاه الى خارج منطقة المعابد بقيت قاعدته من الكونكريت المسلح لذا لا بد من رفعها من منطقة المعابد.
- ٩- ترميم الصحيات العامة لحاجة الموقع الماسة لها خصوصا بعد نشاط الحركة السياحية مؤخراً.

#### رابعاً: اعداد برنامج للمراقبة

من الاشياء ذات التأثير المباشر على الموقع الاثري هي الظروف الجوية والمناخية كذلك نمو النباتات الطبيعية في ارضيات المعابد المكشوفة والتي يتطلب معالجتها وازالتها باستمرار بالإضافة الى وجود مشكلة الرطوبة النازلة من سطوح المباني بسبب وجود تشققات في سطوح المباني الاثرية التي تسمح بتسرب مياه الامطار الى داخل الجدران كذلك مشكلة الرطوبة الصاعدة من ارضيات المعابد ، اما فيما يخص الانشطة البشرية فلا تكاد تذكر لأن حدود الموقع الاثري معروفة لدى جميع سكان المنطقة ولا يوجد مشاريع ذات تأثير مباشر على الموقع الاثري مثل المعامل وغيرها من الانشطة الاخرى.



خامساً: التهديدات المحتملة على البقايا الاثرية الواقعة بين اسوار المدينة الداخلية والخارجية

فيما يخص التهديدات على البقايا الاثرية بين اسوار المدينة فبعد تسييج الموقع بسياج (P.R.C) اصبحت المدينة الثرية محمية من جميع الجهات والدخول الى الموقع يكون من باب واحد في الجهة الشرقية تحت حماية القوات الامنية بالإضافة الى وجود مركز شرطة حماية الاثار حيث يقوم منتسبي المركز بأجراء جولات ميدانية على طول مسار السياج حول المدينة الاثرية لحمايته من اي خروقات قد تحصل

سادساً: اعداد خطة ادارة الموقع وادارة الزوار

فيما يخص ادارة الموقع كان من المفترض ان يتم اعداد خطة لإدارة الموقع بالاشتراك مع بعثة منظمة (ASMEO) العاملة في الموقع الاثري لكن بسبب تأخر عودة البعثة المذكورة اعلاه لعدم توفر التمويل لذلك لم يتم اعداد خطة بعد.

اما فيما يخص ادارة الزوار فمن الضروري ان يكون هناك مركز لاستقبال الزوار وتحديد مساراتهم وتوفير وسائل ايضاح سمعية او مرئية مع توفير كادر من الادلاء السياحيين لمرافقة الوفود السياحية خصوصا بعد نشاط الحركة السياحية في الآونة الاخيرة .

ومن الامور التي يمكن اضافتها الى هذا التقرير فيما يخص النشاطات داخل الموقع الاثري خلال عام ٢٠٢٤ فبتاريخ ٢٩/٢/٢٠٢٤ تم اقامة مهرجان احياء روح الحضر برعاية وزارة السياحة والثقافة والاثار واشراف مباشر من قبل الهيئة العامة

للآثار والتراث ومفتشية اثار وتراث نينوى حيث حضر المهرجان شخصيات مهمة من الحكومة العراقية متمثلة بالسيد رئيس الجمهورية والسيد وزير الثقافة والسياحة والآثار والسيد رئيس الهيئة العامة للآثار والتراث والسيد محافظ نينوى والسيد رئيس مجلس واعضاء مجلس محافظة نينوى وشخصيات اجنبية وشيوخ عشائر وناشطين المجتمع المدني وجمع غفير من كل المحافظات العراقية ( انظر الصورة رقم ٤ )



( صورة رقم ٤ )

محمود عبدالله وردي شبيب

مدير موقع الحضر تراث عالمي

٢٠٢٤/١١/٢٥